

POOR LEGIBILITY

ONE OR MORE PAGES IN THIS DOCUMENT ARE DIFFICULT TO READ
DUE TO THE QUALITY OF THE ORIGINAL

CITY OF MOUNTAIN VIEW

APPLICATION
FOR
SEWER SERVICE CONNECTION

REVISED: 9-15-63

ORDINANCE NO. 175.425

NO. 175.601

& NO. 92.63

A. EXISTING FACILITIES CHARGE: (Interceptor and Trunk Sewers
Account No. 7953 @ \$200/acre)28,057 square feet @ \$0.0046/sq. ft.\$ 129.06B. FRONT FOOTAGE CHARGE:

Account No. 7953

69.09 linear front feet @ \$4.00/f.f.\$ 276.36C. SEWER SERVICE CONNECTION CHARGE:

Account No. 7952

_____ only - 4" V.C.P. Laterals @ \$160.00/each

(By City from main to property line.)

\$ _____

_____ only - 6" V.C.P. Laterals @ \$180.00/each

(By City from main to property line.)

\$ _____

TOTAL

\$ 405.42

REMARKS:

Lateral to be installed by developerIntercepting sewer
by City from main to
property lineApplicant: Standard Oil Co. Address: _____Address of Job: 45 W. El Camino Phone No.: _____

I hereby make application for sewer service connection at the above location.

Signature of Applicant _____

Order taken by _____

Date

4/30/64

- () Finance Dept.
 () Corp. Yard
 () Public Works Pending
 () Public Works Complete
 () Financial Dept. 2nd Copy

15-21

CITY OF MOUNTAIN VIEW

PAID
MAY 1964Rec. No. 36373Amount 405.42By 45 W. ECR

LABOR & MATERIALS

BACK-ME

LA 50R

52 Hrs

MATERIALS

167EE SADDLE

1612 BEND

5, 6" x 4' Joints

1 RUBBER PLUG

吳昌碩

Date Installed

July 1, 1963

Actual Installation Cost \$

LOCATION DIAGRAM

